



FIG.1



(1) State before failure



(2) State after failure of 30A

FIG.2




FIG.3




FIG.4




FIG.5




FIG.6




FIG.7




FIG.8




FIG.9
 (PRIOR ART)




FIG.10
 (PRIOR ART)




FIG.11

(PRIOR ART)




FIG.12 (PRIOR ART)




FIG.14




FIG.15




FIG.16




FIG.17




FIG.18

